

# Church resto

23 May 2016

[www.friendsofdroxfordchurch.org.uk](http://www.friendsofdroxfordchurch.org.uk)



# Bees



bees from above.jpg



bees from below.jpg

# Clock



clock 1.JPG



clock.jpg



removing clock hands 1.jpg



removing clock hands.jpg

# Dormer Windows



dormer 1.jpg



dormer 2 removing rotten wood.jpg



dormer 3.jpg



dormer 4.jpg



dormer.jpg

# Inserting metal bars to strengthen tower



bar inserted and fixed in place.jpg

bar plate being added.jpg

bar plate close-up.jpg



flint - marking out flint to be removed.jpg

flint removed back to brickwork.jpg

hole drilled for bar.jpg



re-filling flint around bars.jpg

re-filling the flint after bar and plates added.jpg

removing flint.jpg

# Inserting metal bars to strengthen tower



removing old mortar for flint repointing.jpg



repointing.jpg

# Misc



Measuring up the bell tower.jpg



view 1.jpg



view.jpg

# Bare roof and repairs before felt and batons



bare roof 2 (2).jpg



bare roof 2.jpg



bare roof repair 1.jpg



bare roof repair.jpg



bare roof.jpg



# Clearing and adding wooden batons



adding wooden roof batons.jpg



clearing old roof batons.jpg



roof batons 3.jpg



roof batons 4.jpg



roof batons 5.jpg



roof batons 6.jpg



roof batons 7.jpg



roof batons 8.jpg



roof batons 9.jpg

# Clearing and adding wooden batons



roof batons 10.jpg



roof batons 1.jpg



roof batons 2.jpg

# Roof felt



attaching roof felt.jpg



roof felt.jpg


# Stripping roof tiles



stripping roof tiles 1.jpg



stripping roof tiles 2.jpg



stripping roof tiles 3.jpg



stripping roof tiles 4.jpg



stripping roof tiles 5.jpg

# Tower Scaffolding



scaffolding 1.jpg



scaffolding 2.jpg



scaffolding 3.jpg